


Date: Tuesday, 30/10/2007 11:05:29 AM
 User: Linda Lacelle

Process Sheet

Customer :	CU-DAR001 Dart Helicopters Services	Drawing Name :	AFT CROSSTUBE
Job Number :	35422		
Estimate Number :	10377		
P.O. Number :	N/A	Part Number :	D2890
This Issue :	30/10/2007	S.O. No. :	N/A
Prsht Rev. :	NC	Drawing Number :	D2890 REV B
First Issue :	N/A	Project Number :	N/A
Previous Run :	35421	Drawing Revision :	B
		Material :	N/A
Written By :		Due Date :	15/11/2007
Checked & Approved By :		Qty:	1
Comment :	Est. D 05.03.21 Removed Bending procedures KJ/JLM	Um:	Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	D6008180	Crosstube extrusion
-----	----------	---------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty	Part #	Description	Batch
1	D6008-180	Crosstube extrusion	B23964

EL 7-10-31

2.0	BENDING	BENDING MACHINE
-----	---------	-----------------

**Comment:** BENDING MACHINE

1-Bend D2890 as per Dwg D2890 and Folio FT002

EL 7-10-31

3.0	QC6	DIMENSIONAL CHECK
-----	-----	-------------------

**Comment:** DIMENSIONAL CHECK

7-10-31 (1)

4.0	LANDING GEAR 1	LANDING GEAR RESOURCE 1
-----	----------------	-------------------------

**Comment:** LANDING GEAR RESOURCE 1

N/A

1-Deburr and Polish

5.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
-----	-----------------	----------------------------

**Comment:** HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

N/A

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 30/10/2007 11:05:29 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT CROSSTUBE

Job Number: 35422

Part Number: D2890

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



N/A



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

7.0

PACKAGING 1

PACKAGING RESOURCE #1



JA-10.31 (1)



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: W/D 35428

(-103)

8.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

DA11/03 (1)

Job Completion



JA 07.10.31

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector



Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries

QACOPY ISSUED

DESIGN		DRAWN BY		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DRAWING NO.		REV. B	
		D2890		SHEET 1 OF 1	
DATE		TITLE		SCALE	
02.10.18		AFT CROSSTUBE		1:20	
A	99.05.21	NEW ISSUE			
B	02.10.18	ADD TANGENT LENGTHS; CHANGE NOTES			

02-10-28

info 55622



NOTES

- 1) MATERIAL: MANUFACTURE FROM D6008-180 ($\phi 3.25$ OD x 0.438 WALL)
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) PART IS SYMMETRIC ABOUT CENTERLINE
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) BEND PROGRESSIVELY WITH MINIMUM OF 3 PASSES
- 6) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE LTD		Work Order: 35422
Description: Crosstube Aft		Part Number: D2890
Inspection Dwg: D2890	Rev: B	Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05



Comments
- Tube is Perfect for B3542B 0205-588-103

QC15 Inspection	
Date	07-10-31

Rev	Date	Change	Revised by	Approved
A	07.02.06	New Issue	KJ/JM	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries